

Notice



- ☐ CORRECTION ☒ PRODUCTION CHANGE
☐ SERVICE FLASH ☐ ADD INFORMATION

FILE NO.

REVISION 0

Please add this notice to the Service Manual listed below.

Category: **COLOR TELEVISION** Date: **OCTOBER / 06 / 2009**

Model: **DP37649** Effective from : Chassis No. **P37649-01**

Destination: **U.S.A. / CANADA** REF : **No. SM780162-01**

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P37649-00. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P37649-00 used in Model DP37649 (SM7800162).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. **088 OP2 Data** should match **21h** in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

- A : Misprint B : Quality Reliability C : Standardization
D : Design E : Add as a possible sub F : Schematic location change
G : Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchangeability	Reason
Page 25, Chassis Electrical Parts List	▲ EL901	Old	1AV4T40C11900	LCD(T370XW02 VC02)	1	NO	D
		New	1AV4T40C00300	LCD(T370XW02 VC00)	1	NO	

For parts or service contact:

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000

November 2009 SMC

Published in Mexico

DP37649, N4PLE, PRODUCT CODE 113018204

REFERENCE No. SM780162-01